

Specification Amendments

On page 12, lines 40-42, please make the following changes:

"As shown, the interconnect pad 150 is positioned at the back or top of the slider/MR head 142 (the slider surface facing the suspension) and is electrically bonded to the conductive..."